

6292806




Figure 1A




Figure 1B

2 / 113

Gulfstream G-IV Library Airworthiness Directives Selection List Cumulative Index					Word Finds
AD Number	Effective Date	Description	Applicable Service Information		
88-02-01 R1	02/13/89	To prevent the potential display and use of hazardously misleading information from	GC SH IV-53A		
88-20-04	05/11/81	To prevent loss of engine power while flying in icing conditions	GC SH IV-51A		
89-02-12	04/03/89	To prevent premature turns toward the runway while conducting ILS approaches	GC SH IV-110		
89-04-10	04/03/89	To prevent inadvertent pusher activation during rotation on takeoff	GC CA IV-4		
89-05-05	05/08/89	To ensure that the engine fire extinguishing system electrical power leads are properly connected	GC CA IV-5		
90-02-05	02/13/90	To prevent an airplane taking off in an unsafe takeoff configuration	GC SH IV-122		
<div>Help Navigator Bookmark Inquiry Print Reverse Course List History Zoom Graphic</div>					

Figure 2

ATP Navigator
<div><div>License Agreement</div><div><p>Before using this product, do you accept the terms and conditions as specified in the License Agreement?</p><div><div><input type="button" value="Yes"/></div><div><input type="button" value="No"/></div><div><input type="button" value="Review"/></div></div></div></div>

Figure 3




Figure 4

Gulfstream G-IV Library - 06/01/

User Login

Name:

Password:

☐ User Utilities

OK

Exit

Figure 5

Figure 6




Figure 7




Figure 8




Figure 9




Figure 10




Figure 11

<div> <div> </div> <div> </div> </div>			<div> <div> <div>ATP - US Federal Regulatory Library</div> <div>History List</div> <div>MS041192</div> </div> <div> </div> </div>	
Document ID	Title	Issue Date		
FR 49	Part 49 - Recording of Aircraft Titles and Security Documents	10/17/91		
AC 65-19E	Inspection Authorization Study Guide	04/08/87		
AD 89-02-12	To prevent premature turns toward the runway	01/24/89		
GC SH IV-110	To prevent premature turns toward the runway	02/24/89		
GC CA IV-5	To provide a one-time inspection for identification...	02/02/89		
			<div> <div> <div>Help</div> <div> </div> </div> <div> <div>Navigator</div> <div> </div> </div> <div> <div>Bookmark</div> <div> </div> </div> <div> <div>Inquiry</div> <div> </div> </div> <div> <div>Print</div> <div> </div> </div> <div> <div>Reverse Course</div> <div> </div> </div> <div> <div>List</div> <div> </div> </div> <div> <div>History</div> <div> </div> </div> <div> <div>Zoom</div> <div> </div> </div> <div> <div>Graphic</div> <div> </div> </div> </div>	

Figure 12




Figure 13




Figure 14




Figure 15




Figure 16




Figure 17




Figure 18


Profile ID: N1ATP






Type	Manufacturer	Model
Airframe		
<input checked="" type="checkbox"/> Multi Engine	Gulfstream Aero	G-IV
<input type="checkbox"/> Auxiliary Power Unit	Garrett	GTCP 36-150(G)
Engine 1		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9
Engine 2		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9

Full Profile


Active: Yes **Profile Created:** 11/20/91 **Changed:** 04/10/92

Operator: Aircraft Technical Publishers
Contact: Michael Sandifer
Title: VP Marketing and Sales
Address: 101 South Hill Drive
City: Brisbane **State:** CA **ZIP:** 94005





Help




Navigator




Bookmark



Inquiry



Print



Reverse Course




Figure 19




Figure 20

Gulfstream G-IV Library - 06/01/


Profile ID: N1ATP


Type	Manufacturer	Model
Airframe		
<input checked="" type="checkbox"/> Multi Engine	Gulfstream Aero	G-IV
<input type="checkbox"/> Auxiliary Power Unit	Garrett	GTCP 36-150(G)
Engine 1		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9
Engine 2		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9


Full Profile


Active: Yes Profile Created: 11/20/91 Changed: 04/10/92


Operator: Aircraft Technical Publishers
 Contact: Michael Sandifer
 Title: VP Marketing and Sales
 Address: 101 South Hill Drive
 City: Brisbane State: CA ZIP: 94005



Publications


Logbook


Diagnosis


Troubleshoot


Profile Utility



Publication List

Document Types:

☐ Federal Regulatory

☐ Airworthiness Directive

☐ Service Information





☐ Type Certificate

☐ Supplemental Type Certificates



Selection List

Word Search

Cancel

Help
Navigator
Bookmark
Inquiry

Print
Reverse Course

Figure 21

Gulfstream G-IV Library - 06/01/

Profile ID: NTATP

Type	Manufacturer	Model
Airframe		
<input checked="" type="checkbox"/> Multi Engine	Gulfstream Aero	G-IV
<input type="checkbox"/> Auxillary Power Unit	Garrett	GTCP 36-150(G)
Engine 1		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9
Engine 2		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9

Full Profile

Active: Yes **Profile Created:** 11/20/91 **Changed:** 04/10/92

Operator: Aircraft Technical Publishers
Contact: Michael Sandifer
Title: VP Marketing and Sales
Address: 101 South Hill Drive
City: Brisbane **State:** CA **ZIP:** 94005

Word Search

Specify Search Criteria:

Select Issues: Date:

Search: ☐ Headers ☐ Text

Word Search Expression:

flap actuator

Word List: Link: or

OK Cancel

Publications

Logbook

Diagnosis

Troubleshoot

Profile Utility

Help

Navigator

Bookmark











Inquiry

Print

Reverse Course

Figure 22

Gulfstream G-IV Library				
Airworthiness Directives Selection List				
Cumulative Index				
AD Number	Effective Date	Description	Applicable Service Information	Word Finds
88-02-01 R1	02/13/89	To prevent the potential display and use of hazardously misleading information from	GC SH IV-53A	
88-20-04	05/11/81	To prevent loss of engine power while flying in icing conditions	GC SH IV-51A	
89-02-12	04/03/89	To prevent premature turns toward the runway while conducting ILS approaches	GC SH IV-110	
89-04-10	04/03/89	To prevent inadvertent pusher activation during rotation on takeoff	GC CA IV-4	
89-05-05	05/08/89	To ensure that the engine fire extinguishing system electrical power leads are properly connected	GC CA IV-5	
90-02-05	02/13/90	To prevent an airplane taking off in an unsafe takeoff configuration	GC SH IV-122	








Figure 23

Gulfstream G-IV Library - 06/01/

Profile ID: N1ATP

Type	Manufacturer	Model
Airframe	Gulfstream Aero	G-IV
<input checked="" type="checkbox"/> Multi Engine	Garrett	GTCP 36-150(G)
<input type="checkbox"/> Auxiliary Power Unit		
Engine 1	Rolls Royce	Tay 611-8
<input type="checkbox"/> Turbine	Grumman	G-634-9
<input type="checkbox"/> Thrust Reverser		
Engine 2	Rolls Royce	Tay 611-8
<input type="checkbox"/> Turbine	Grumman	G-634-9
<input type="checkbox"/> Thrust Reverser		

Full Profile

Active: Yes **Profile Created:** 11/20/91 **Changed:** 04/10/92

Operator: Aircraft Technical Publishers
Contact: Michael Sandifer
Title: VP Marketing and Sales
Address: 101 South Hill Drive
City: Brisbane **State:** CA **ZIP:** 94005

Inspection Aids

Select Inspection Aid:

☐ Inspection History

☐ AD Compliance History

☐ Service Information Compliance History

☐ Appliance AD Applicability

☐ Squawk History

OK Cancel

Publications Logbook Diagnosis Troubleshoot Profile Utility

Help Navigator Bookmark Inquiry Print Reverse Course

Figure 24

▼▲

Gulfstream G-IV Library - 06/01/

Choose Service History Record:

Profile ID: N1ATP

Inspection

Date

Type

This Flight

Hours

Cycles

Freq.

TSN

Accumulative Totals

TSO

Freq.

TSN

TSO

12/12/12	skipewndfolkvurfd	12345	12345	alskfhmylth	12345	alskfhmylth	12345	alskfhmylth	12345	12345	12345	12345	12345

New

Save

Reset

Delete

Search

Quit

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 25

Choose Service History Record:

Inspection

Date

Type

Hours

Cycles

Freq.

TSN

Accumulative Totals

TSO

Freq.

TSN

TSO

12/12/12	skipewndfollyurfd	12345	12345	alskfhmviyh	12345	12345	alskfhmviyh	12345	12345	12345	12345

Profile ID:

N1ATP

New

Save

Reset

Delete

Search

Quit

Create New Inspection Record:

Profile ID:

Inspection:

Inspection Type:

Date:

This Flight:

Hours:

Cycles:

Frequency:

Frequency:

Frequency:

TSN:

TSN:

TSN:

TSO:

TSO:

TSO:

Facility:

Contact:

Address:

Repair Station #:

Title:

Phone:

FAX:

Country:

City:

State:

Zip:

Comments:

Comment File:

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 26

Choose AD Compliance Record: _____ Profile ID: N1ATP									
Document	Description	Issue Date	Action	Date	Hours	Compliance Freq.	Units		
GC CB 92-04-03 R1		12/12/91	On-Condition	2/20/92	12345	APU Hours	12345	+	

Find ADs

New Event

Save

Reset

Delete

Search

Quit

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 27

Gulfstream G-IV Library - 06/01/																																									
Choose AD Compliance Record: _____ Profile ID: NTATP					<div style="display: flex; justify-content: space-between; margin: 0;"> Find ADs New Event Save Reset Delete Search Quit </div>																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Document</th> <th style="width: 25%;">Description</th> <th style="width: 10%;">Issue Date</th> <th style="width: 10%;">Action</th> <th style="width: 10%;">Date</th> <th style="width: 10%;">Compliance Hours</th> <th style="width: 10%;">Freq.</th> <th style="width: 10%;">Units</th> </tr> </thead> <tbody> <tr> <td>GC CB 92-04-03 R1</td> <td></td> <td>12/12/91</td> <td>On-Condition</td> <td>2/20/92</td> <td>12345</td> <td>APU Hours</td> <td>12345</td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>										Document	Description	Issue Date	Action	Date	Compliance Hours	Freq.	Units	GC CB 92-04-03 R1		12/12/91	On-Condition	2/20/92	12345	APU Hours	12345																
Document	Description	Issue Date	Action	Date	Compliance Hours	Freq.	Units																																		
GC CB 92-04-03 R1		12/12/91	On-Condition	2/20/92	12345	APU Hours	12345																																		
<div style="display: flex;"> <div style="flex: 1;"> <p>—Create AD Compliance Event Record: _____</p> <p>Profile ID: </p> <p>Component: </p> <p>Manufacturer: </p> <p>Part Number: </p> <p>Doc ID: </p> <p>Compliance: </p> </div> <div style="flex: 1;"> <p>Inspection: </p> <p>Squawk: </p> <p>Model: </p> <p>Serial Number: </p> <p>Description: </p> </div> </div>																																									
<div style="display: flex;"> <div style="flex: 1;"> <p>Type: </p> <p>Date: / /</p> <p>Recurring: <input type="checkbox"/> Last Complied Date: / /</p> <p>Next Compliance Date: / /</p> <p>Operation: </p> <p>Authorization: Type: </p> <p>Comments: </p> </div> <div style="flex: 1;"> <p>Action: </p> <p>Frequency: Units: </p> <p>Frequency: Units: </p> <p>Frequency: Units: </p> <p>Method: </p> <p>By: </p> </div> </div>																																									
<div style="display: flex; justify-content: space-between; align-items: center;"> <div> <p>Help </p> <p>Navigator </p> <p>Bookmark </p> <p>Inquiry </p> </div> <div> <p>Print </p> <p>Reverse Course </p> </div> </div>																																									

Figure 28

▼▲

Gulfstream G-IV Library - 06/01/

Choose SI Compliance Record: _____ Profile ID:

N1ATP

Document	Description	Issue Date	Action	Date	Hours	Freq.	Units
GC CB 92-04-03 R1		12/12/91	On-Condition	2/20/92	12345	APU Hours	12345

Find SIs

New Event

Save

Reset

Delete

Search

Quit

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 29

Gulfstream G-IV Library - 06/01/

Choose SI Compliance Record: Profile ID: N1ATP

Document	Description	Issue Date	Action	Date	Hours	Freq.	Units
GC CB 92-04-03 R1		12/12/91	On-Condition	2/20/92	12345	APU Hours	12345

Change SI Compliance Event Record:

Profile ID: N1ATP

Component:

Manufacturer:

Part Number:

Doc ID:

Description:

Compliance:

Type:

Date: / /

Recurring: ☐ Last Complied Date: / /

Next Compliance Date: / /

Operation:

Authorization: Type:

Comments:

Inspection:

Squawk:

Model:

Serial Number:

Action:

Frequency: Units:

Frequency: Units:

Frequency: Units:

Method:

By:

Find SIs

New Event

Save

Reset

Delete

Search

Quit














Figure 30

Figure 31

Figure 32

Gulfstream G-IV Library - 06/01/				
Appliance AD Applicability: _____		Profile ID: <input type="text" value="N1ATP"/>		
AD	Manufacturer	Description	Inspection	Applicability Comp. Cmpl. Insp.
Air Conditioner				
91-01-06				
80-12-04				

Create New Component Record:

Profile ID: Active: ☐ Component Record Created:

Component Category: Assigned Category: Component Record Changed:

Component Type:

Manufacturer: Certification #:

Model: Description:

Part Number: Warranty Expires:

Serial Number: Placed in Service:

Manufacture Date: TSN:

Time Since New Hours: TSO:

Time Since Overhaul Hours: Component Installed Hours:

Component Installed Date: Removed:

Component Removed Date:

Find ADs

New Component

Save

Reset

Delete

Search

Quit

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 33

Gulfstream G-IV Library - 06/01/

Choose Squawk History Record: Profile ID: N1ATP

Squawk ID	Date	ATA Ref.	A/C Hours	Freq.	Units	Corrected Date	Description
34255-345-001	04/18/86	72	7,258	E Cycles	9,482	08/13/86	Fluctuating Torque Indication
34255-635-468	02/23/87	72	7,825	E Cycles	10,637	05/27/87	Low Oil Pressure
63548-872-569	06/24/89	72	8,734	E Cycles	11,478	09/20/89	Slow acceleration to idle
23646-738-426	11/21/90	72	9,420	E Cycles	2,360	02/14/91	Intermittent temperature indication

New Save Reset Delete Search Quit

Help Navigator Bookmark Inquiry Print Reverse Course

Figure 34

Gulfstream G-IV Library - 06/01/

Choose Squawk History Record: Profile ID: N1ATP

Squawk ID	Date	ATA Ref.	A/C Hours	Freq.	Units	Corrected Date	Description
34255-345-001	04/18/86	72	7,258	E Cycles	9,482	08/13/86	Fluctuating Torque Indication
34255-635-468	02/23/87	72	7,825	E Cycles	10,637	05/27/87	Low Oil Pressure
63548-872-569	06/24/89	72	8,734	E Cycles	11,478	09/20/89	Slow acceleration to idle
23646-738-426	11/21/90	72	9,420	E Cycles	2,360	02/14/91	Intermittent temperature indication

New

Save

Reset

Delete

Search

Quit

Change Squawk History Record:

Profile ID: N1ATP

Component: +

Manufacturer:

Part Number:

Squawk Date: / / A/C Hours: Units:

Frequency: Units:

Squawk Reported By:

Description:

Squawk:

Model:

Serial Number:

ATA Reference:

Frequency: Units:

Squawk Corrected Date / / A/C Hours: Inspection:

Squawk Corrective Action: Comment File:

Help

Navigation

Logbook

Inquiry

Print

Refresh

Close

Figure 35

Gulfstream G-IV Library - 06/01/

Profile ID: **N1ATP**

Type	Manufacturer	Model
Airframe		
<input checked="" type="checkbox"/> Multi Engine	Gulfstream Aero	G-IV
<input type="checkbox"/> Auxillary Power Unit	Garrett	GTCP 36-150(G)
Engine 1		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9
Engine 2		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9

Full Profile

Active: Yes Profile Created: 11/20/91 Changed: 04/10/92

Operator: Aircraft Technical Publishers
 Contact: Michael Sandifer
 Title: VP Marketing and Sales
 Address: 101 South Hill Drive
 City: Brisbane State: CA ZIP: 94005

Word Search

Specify Search Criteria:

Select Issues: After Date:

Search: ☐ Headers ☐ Text

Word Search Expression: flap actuator

Word List: Link: or

OK Cancel

Publications Logbook Diagnosis Troubleshoot Profile Utility

Help Navigator Bookmark Inquiry Print Reverse Course

Figure 36

Figure 39

Figure 39

Gulfstream G-IV Library - 06/01/			
<input type="button" value="New Profile"/> <input type="button" value="New Component"/> <input type="button" value="Save"/> <input type="button" value="Reset"/> <input type="button" value="Delete"/> <input type="button" value="Search"/> <input type="button" value="Quit"/>			
Choose Profile or Component Record:			
Profile ID: <input type="text" value="N1ATP"/>	Category: <div style="border: 1px solid black; padding: 2px;"> Airframe Airframe Engine 1 Engine 1 Engine 2 Engine 2 </div>	Type: <div style="border: 1px solid black; padding: 2px;"> Multi Engine Auxiliary Power Unit Turbine Thrust Reverser Turbine Thrust Reverser </div>	Manufacturer: <div style="border: 1px solid black; padding: 2px;"> Gulfstream Aero Garrett Rolls Royce Grumman Rolls Royce Grumman </div>
Model: <div style="border: 1px solid black; padding: 2px;"> G-IV GTCB 36-150(G) Tay 611-8 G-634-9 Tay 611-8 G-634-9 </div>			
Change Component Record:			
Profile ID: <input type="text" value="N1ATP"/>		Active: <input type="checkbox"/> Y <input type="checkbox"/> N	
Component Record Created: <input type="text" value=""/> / /		Component Record Changed: <input type="text" value=""/> / /	
Component Category: <input type="text" value=""/>		Assigned Category: <input type="text" value=""/>	
Component Type: <input type="text" value=""/>		Manufacturer: <input type="text" value=""/>	
Model: <input type="text" value=""/>		Certification #: <input type="text" value=""/>	
Part Number: <input type="text" value=""/>		Description: <input type="text" value=""/>	
Serial Number: <input type="text" value=""/>		Warranty Expires: <input type="text" value=""/> / /	
Manufacture Date: <input type="text" value=""/> / /		Placed in Service: <input type="text" value=""/> / /	
Time Since New Hours: <input type="text" value=""/>		TSN: <input type="text" value=""/>	
Time Since Overhaul Hours: <input type="text" value=""/>		TSD: <input type="text" value=""/>	
Component Installed Date: <input type="text" value=""/> / /		Component Installed Hours: <input type="text" value=""/>	
Component Removed Date: <input type="text" value=""/> / /		Removed: <input type="text" value=""/>	

Figure 40

Gulfstream G-IV Library - 06/01/

Profile ID: **N1ATP**

Type	Manufacturer	Model
Airframe		
<input checked="" type="checkbox"/> Multi Engine	Gulfstream Aero	G-IV
<input type="checkbox"/> Auxiliary Power Unit	Garrett	GTCP 36-150(G)
Engine 1		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9
Engine 2		
<input type="checkbox"/> Turbine	Rolls Royce	Tay 611-8
<input type="checkbox"/> Thrust Reverser	Grumman	G-634-9

Full Profile

Active: Yes Profile Created: 11/20/91 Changed: 04/10/92

Operator: Aircraft Technical Publishers
 Contact: Michael Sandifer
 Title: VP Marketing and Sales
 Address: 101 South Hill Drive
 City: Brisbane State: CA ZIP: 94005

Copy Profile From:
☐ Diskette Drive "A"
☐ Diskette Drive "B"
☒ System Hard Drive

Copy Profile To:
☒ Diskette Drive "A"
☐ Diskette Drive "B"
☐ System Hard Drive

Select Profile to Copy:
 N1ATP
 N1ATP
 N2494G
 N325BA

Copy Cancel

Publications Logbook Diagnosis Troubleshoot Profile Utility

Help Navigator Bookmark Inquiry Print Reverse Course

Figure 41




Figure 42




Figure 43




Figure 44




Figure 45




Figure 46

Gulfstream G-IV Library - 06/01/

AIRWORTHINESS DIRECTIVES

ASSOCIATED SERVICE INDEX

TYPE CERTIFICATE

SUPPLEMENTAL TYPE CERTIFICATE

ADVISORY CIRCULARS

FEDERAL AVIATION REGULATIONS

ORDERS

Airworthiness Directives - Browse

Browse
 Search

Choose one of the following indexes:

☐ Cumulative ☒ Appliance ☐ Biweekly

☐ ATP Eiche Cumulative Index

Specify starting-place in browse list:

Appliance	Engine Gage Units
Category:	
Manufacturer:	Garwin, Inc.
Model:	P/N 22-802-022
AD#:	P/N 22-802-022
	P/N 22-802-03
	P/N 22-802-04
	P/N 22-802-05
	P/N 22-802-06
	P/N 22-802-07
	P/N 22-802-08
	P/N 22-802-09

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

Figure 47

1. *Journal of the American Medical Association*, 283: 2669-2674, 2000.

[illegible]




Figure 49

ATP - US Federal Regulatory Library			
Airworthiness Directives Selection List - 04/00/92			
Small Aircraft and Rotorcraft Biweekly Listing			
AD Number	Manufacturer	Subject	General Applicability
<u>Issue Number 92-04</u>			
91-02-07 R1	Bell - Correction	39-6339	Model: 204B, 205A, 205A-1, and 212 helicopters
92-04-06	Piper	39-6453	Model: PA-25, -25-235, and -25-260
92-04-09	Grob	39-6447	Model Twin Astie and Twin Aster Trainer, G103 Twin II, and G103A Twin II Acro gliders
92-04-11	Piper	39-6455	Model: PA-42, PA-42-720, and PA-42-720R
92-04-11	Cessna	39-6445	Model: 310, 320, 340, 401, 402, 411 414, 421
92-04-14	British Aerospace	39-6434	Model: Jetstream HP 137 MX 1, 200, 3101, and 3201

Help

Navigator

Bookmark

Inquiry

Print

Reverse Course

List

History

Zoom

Graphic

Figure 50

ATP - US Federal Regulatory Library Airworthiness Directives Selection List Proposed AD's					
Docket Number	Fed. Reg. Date	Action Date	Description		
92-CE-05-AD	02/27/92	05/06/92	Replacement of all Garrett AirResearch improperly overhauled aircraft starters procured from Classic Aviation with an approved part		
91-CE-89-AD	03/02/92	05/04/92	Inspection of possibly severed elevator trim tab guide on Piper models PA-46-310P (Malibu) and PA-16-350P (Mirage)		
91-CE-101-AD	03/02/92	05/04/92	Replacement of certain empennage countersunk rivets on Piper models PA-46-310P (Malibu) and PA-16-350P (Mirage) as indicated in Piper Service Bulletin 944		
91-CE-96-AD	03/02/92	05/04/92	To prevent failure air driven attitude gyro and autopilot systems on Piper models PA-46-310P (Malibu) and PA-16-350P (Mirage) as indicated in Piper Service Bulletin 947A		

Figure 51




Figure 52

ATP - US Federal Regulatory Library Alert Customer Bulletin Selection List Gulfstream			
Issue Number	Issue Date	Description	Applicable Status ATA AD
<u>Gulfstream Aerospace Corporation - Alert Customer Bulletins</u>			
Model G-1159 (G-II)			
II-20	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory 26 89-05-05
Model G-1159A (G-III)			
III-4	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory 26 89-05-05
III-6A	10/01/91	Electrical power. Feeder cable inspection	Mandatory 24 91-25-05
Model G-1159B (G-IIB)			
II-20	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory 26 89-05-05
Help		Navigator	Bookmark
Inquiry		Print	Reverse Course
List		History	Zoom
Graphic			

Figure 53

ATP - US Federal Regulatory Library Alert Customer Bulletin Selection List Gulfstream			
Issue Number	Issue Date	Description	Applicable Status ATA AD
Alert Customer Bulletins			
IV-4	02/01/89	Angle of attack. Stall Warning Computer (SWC) part number 965-0041-035	Mandatory 27 89-04-10
IV-5	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory 26 89-05-05
IV-7A	10/01/91	Electrical power. Feeder cable inspection	Mandatory 24 91-25-05

Figure 54




Figure 55

ATP - US Federal Regulatory Library Supplemental Type Certificate Index Aircraft				
Aircraft Make, Model & T.C. No.	STC No.	Description	RG.	STC Holder
<u>GULFSTREAM AMERICAN</u>				
G-44, AA-1, AA-1A, AA-1B, AA-5, AA-5A, T.C. A-734 A11EA, A16EA	SA308EA	Installation of A.R.P. Industries carburetor ice detection system 105AP in single and twin aircraft and single engine helicopters powered by Continental, Franklyn, and Lycoming type engines equipped with Marvel Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/20/787	EA	Alfred R. Puccinelli Co. DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
G-44; T.C. A-734	SA366AL	Installation of Cessna P/N AL 1223000-7 and -8 wing tips.	AL	George Pappas Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501

Help
 Navigator
 Bookmark
 Inquiry
 Print
 Reverse Course

List

 History

 Zoom

 Graphic

Figure 56




Figure 57




Figure 58

ATP - US Federal Regulatory Library Alert Customer Bulletin Selection List Gulfstream			
Issue Number	Issue Date	Description	Applicable Status ATA AD
Model G-IV			
IV-4	02/01/89	Angle of attack. Stall Warning Computer (SWC) part number 965-0041-035	Mandatory 27 89-04-10
IV-5	02/02/89	Fire protection. Engine fire extinguisher system	Mandatory 26 89-05-05
IV-7A	10/01/91	Electrical power. Feeder cable inspection	Mandatory 24 91-25-05
Gulfstream Aerospace Corporation - Customer Bulletins			
Model G-159 (G-I)			
I-11	14/02/79	To prevent a potential hazard caused by inability to discharge the engine or APU fire extinguisher bottles.	Active 26 79-06-03
I-208A	11/18/71	Inspection of trim tab actuators n/n	Active 27 72-24-04
<div> <div> </div> <div> List History Zoom Graphic </div> </div>			

Figure 59




Figure 60

ATP - US Federal Regulatory Library Supplemental Type Certificate Index Aircraft				
Aircraft Make, Model & T.C. No.	STC No.	Description	RG.	STC Holder
<u>GULFSTREAM AMERICAN</u>				
G-44, AA-1, AA-1A, AA-1B, AA-5, AA-5A, T.C. A-734 A11EA, A16EA	SA308EA	Installation of A.R.P. Industries carburetor ice detection system 105AP in single and twin aircraft and single engine helicopters powered by Continental, Franklyn, and Lycoming type engines equipped with Marvel Schebler MA-2, MA-3, MA-3SPA, MA-4, MA-4-5, MA-6 and HA-6 series carburetors. Amended 10/20/787	EA	Alfred R. Puccinelli Co. DER 1-145 36 Bay Drive East Huntington, L.I., NY 11743
G-44; T.C. A-734	SA366AL	Installation of Cessna P/N AL 1223000-7 and -8 wing tips.	AL	George Pappas Aircraft Rebuilders P.O. Box 3567 Anchorage, AK 99501

Help
 Navigator
 Bookmark
 Inquiry
 Print
 Reverse Course

List
 History
 Zoom
 Graphic

Figure 61




Figure 62



Figure 63

<div>ATP - US Federal Regulatory Library Advisory Circular Selection List - 02/00/92 AC 65-19E - Inspection Authorization Study Guide</div>		<div>ATP</div>	
Chapter/Section	Title		
AC 65-19E - Inspection Authorization Study Guide			
Introductory Information			
Chapter 1	Eligibility, Issuance, Renewal, and Change of Fixed Base		
<div>1 Eligibility 2 Insurance 3 Duration 4 Renewal 5 Change of Fixed Base</div>			
Chapter 2	Ten Suggestions for Taking the IA Test		
Chapter 3	Basic Functions of an IA		
<div>1 General 2 Approving Major Repairs and Major Alterations 3 Annual Load Determination</div>			
<div>Help Navigator Bookmark Inquiry Print Reverse Course</div>		<div>List History Zoom Graphic</div>	

Figure 64




Figure 65




Figure 66

ATP - US Federal Regulatory Library Federal Aviation Regulations Selection List Proposed FARs				
Docket Number	Fed. Reg Date	Action Date	Description	FAR Parts Effectivity
23345	09/01/91	09/30/91	Primary Category Aircraft	21, 36, 43, 91, 141, 147
26530	04/09/91	10/07/91	Improved Access to Type III Exits	25, 121, 135

Figure 67




Figure 68













 ATP - US Federal Regulatory Library Hazardous Materials Selection List Title 49 Subchapter C Parts 171 and 172			
Part/Subpart/Section	Topic		
Part 171	General Info, Regulations & Special Programs Admin, DOT	Parts 171 and 172 - Hazardous Materials	
.01	Purpose and Scope		
.02	General Requirements		
.03	Hazardous Waste		
.04	Changes in specifications for Tank Cars		
.05	Procedure Covering Tank Car Construction		
.07	Matter Incorporated by Reference		
.08	Definitions and Abbreviations		
.09	Rules of Construction		
.10	Flammable/Combustible Liquids Onboard Vessels		
.11	Use of ICAO Technical Instructions		
.12	Import and Export Shipments		
.12A	Canadian Shipments and Packaging		
.13	Emergency Regulations		
.14	Specification Markings		
.15	Immediate Notice-Certain Hazardous Materials Incidents		
.16	Detailed Hazardous Materials Incident Database		
Help  Navigator  Bookmark  Inquiry  Print  Reverse Course 		List  History  Zoom  Graphic 	

Figure 69

ATP - US Federal Regulatory Library Hazardous Materials Selection List Proposed Amendments					FAR Parts Effectivity
Docket Number	Fed. Reg Date	Action Date	Description		
HM-184F	02/16/92	02/18/92	Implementation of the International Civil Aviation Organization's Technical Instructions	171...	
HM-208	11/07/91	11/26/91	Hazardous Materials Transportation Registration and Fee Assessment Program; Additional Hearing Date	171..	
HM-208	10/10/91	10/21/91	Hazardous Materials Transportation Registration and Fee Assessment Program;	171..	
HM-166X	09/07/91	10/07/91	Transportation of Hazardous Materials; Proposed Miscellaneous Amendments	171, 172...	
HM-1891	10/01/90	10/01/90	Hazardous Materials Regulations; Editorial Corrections and Clarifications	171, 172...	

Figure 70

ATP - US Federal Regulatory Library Orders Selection List				
Order Number	Rev.	Title	Issued By	Revised Date
2150.3A	6	Compliance and Enforcement Program	AGC-200	9010
8020.11	13	Aircraft Accidents and Incidents - Notification, Investigation, and Reporting	AFS-100	8712
8130.2B	11	Airworthiness Certification of Aircraft and Related Approvals	AWS-200	8910
8300.10	5	Airworthiness Inspectors Handbook	AFS-500	9011
8400.10	5	Air Transportation Operators Inspector's Handbook	AFS-500	9008
8700.1	7	General Aviation Operations Inspector's Handbook	AFS-500	9010

Figure 71




Figure 72














		Gulfstream G-IV Maintenance Manual Maintenance Manual Selection List Chapter 32 - Landing Gear		
Chapter/Section/Subsection	Title			Word Finds
<h2 style="text-align: center;">CHAPTER 32 -- LANDING GEAR</h2>				
<h3>32-0-0 Landing Gear</h3>				
<h4>DESCRIPTION / OPERATION</h4>				
<ol style="list-style-type: none"> 1. General Operation 2. Operation 3. Ground Safety Lock Provisions 4. Tie Down Provisions 5. Jacking Provisions 				
<h4>FAULT ISOLATION</h4>				
<ol style="list-style-type: none"> 1. Fault Isolating the Landing Gear System 				
<h4>MAINTENANCE PRACTICES</h4>				
<ol style="list-style-type: none"> 1. General 2. Landing Gear -- Normal and Emergency -- Functional Test 				
<h3>32-1-0 Main Gear and Doors</h3>				
<h4>DESCRIPTION / OPERATION</h4>				
Help 	Navigator 	Bookmark 	Inquiry 	Print 
Reverse Course 		List 	History 	Zoom 
		Graphic 		

Figure 73




Figure 75














Gulfstream G-IV Illustrated Parts Catalog Illustrated Parts Catalog Table of Contents Chapter 32 - Landing Gear		Chapter/Section/Sheet/View
		
Subject	Part Nomenclature	
CHAPTER 32 - LANDING GEAR		
NOSE GEAR		32-01-01
Nose	Landing Gear Installation	32-01-02-A
	Uplock Latch Mechanism	32-01-02-B
	Door Control Valve Spring Rod Assembly	32-01-03-C
	Landing Gear Sequencing Arm	32-01-03-D
	Locking Pins	32-01-03-E
	Steering Unit and Mounting Brackets	32-01-04-F
	Nose Wheel Assembly	32-01-04-G
	Valve Stem	32-01-04-H
	Steering and Damper Assembly	32-02-01
Door	Installation	32-03-01
Nose	Landing Gear Assembly	32-03-01-A
	Tie Down Provisions	32-03-01-B
	Actuator Pin (on trunnion assembly)	32-03-02-C
	Truss Brace Assemblies	32-03-03-D
	Shock Strut and Trunnion	32-03-04-E
	Piston	32-03-04-F
	Axle Fitting Assembly	
MAIN GEAR		32-04-01
Main	Landing Gear Installation	32-04-02-A
	Latch Assembly (uplock)	32-04-02-B
	Uplock Mechanism Fitting Assembly	
          		

Figure 76















Figure 77

Gulfstream G-IV Library						
Aircraft Service Changes Selection List						
Issue Number	Issue Date	Description	Status	Applicable ATA	AD	Word Finds
IV-107	06/13/90	Lighting. Thrust reverser lights capsules- Replacement	Recommend	33		
IV-108	Cancelled					
IV-109	Cancelled					
IV-110	01/24/89	Auto flight. Electronic display controllers	Mandatory	22	89-02-12	
IV-111	04/27/89	Hydraulics. Ground spoiler hydraulic plumbing - Modification	Optional	24		
IV-112	06/09/89	Electrical Power. 300 Amp transformer- Rectifier with increase voltage capability	Optional	24		
IV-112 amend 1	12/21/90	Electrical Power. 300 Amp transformer- Rectifier with increase voltage capability	Optional	24		
113	03/22/91	Flight Controls. Aileron/Spoiler input hall crank - Lubrication provisions	Optional	27		
<div> <div>Help</div> <div>Navigator</div> <div>Bookmark</div> <div>Inquiry</div> <div>Print</div> <div>Reverse Course</div> <div>List</div> <div>History</div> <div>Zoom</div> <div>Graphic</div> </div>						

Figure 78

ATP Federal Regulatory Library

Search Options

Note: Non-Aircraft specific publications will disregard manufacturer and model criteria

Select One or More Criteria:

Manufacturer:

Model:


Select Pubs Issued: Date:


After


Search: ☒ Headers ☐ Text


Word Search Expression:


Word List: Link: or

Help 

Navigator 

Bookmark 

Inquiry 

Print 


Reverse Course 

Figure 79






Figure 80

ATP Federal Regulatory Library

 Browse  Search

A D Search Options

Select One or More Criteria:

Sort by:

Size:

Category:

Manufacturer:

Model:

AD#:

TC #:

Serial #:

Amendment #:

Docket #:

Select ADs Issued: Issue Date:

After

Show Word Search Options

OK Cancel

Airworthiness Directives

Related Service Information

TYPE CERTIFICATES

Supplemental Type Certificates

ADVISORY CIRCULARS

Federal Aviation Regulations

Hazardous Materials

FAA HANDBOOKS







Help  Navigator  Bookmark  Inquiry  Print  Reverse Course 

Figure 81




Figure 82

ATP Federal Regulatory Library

Airworthiness Directives
Related Service Information
TYPE CERTIFICATES
Supplemental Type Certificates
ADVISORY CIRCULARS
Federal Aviation Regulations
Hazardous Materials
FAA HANDBOOKS

Service Information Search Options

Select One or More Criteria:

Manufacturer:

Issue Type:

Model:

Issue #:

Serial #:

Select SI Issued: After Date:

Search: ☒ Headers ☐ Text

Word Search Expression:

Word List: Link: or

OK Cancel

Help Navigator Bookmark Inquiry Print Reverse Course

Browse Search

Figure 83



ATP Federal Regulatory Library

Type Certificate Search Options

Select One or More Criteria:

Sort Order: Cumulative

Volume: []

Manufacturer: []

TC #: []

Model: []

Region: []

Select TCs Issued: After [] Date: []

Search: ☐ Headers ☒ Text

Word Search Expression: flap actuator

Word List: [] Link: [] or []

OK Cancel

Airworthiness Directives

Related Service Information

TYPE CERTIFICATES

Supplemental Type Certificates

ADVISORY CIRCULARS

Federal Aviation Regulations



Hazardous Materials

FAA HANDBOOKS

Help Navigator Bookmark Inquiry Print Reverse Course

Figure 84

ATP Federal Regulatory Library

 Browse  Search

STC Search Options

Select One or More Criteria:

Category:

Manufacturer:

Model:

STC #:

Region:

Select TCs Issued: After Date:

Search: ☐ Headers ☒ Text

Word Search Expression:

Word List: Link: or

OK Cancel

Airworthiness Directives

Related Service Information

TYPE CERTIFICATES

Supplemental Type Certificates

ADVISORY CIRCULARS

Federal Aviation Regulations

Hazardous Materials

FAA HANDBOOKS







Help  Navigator  Bookmark  Inquiry  Print  Reverse Course 

Figure 85




Figure 86




Figure 87






Figure 88

ATP Federal Regulatory Library

 Browse  Search

Hazardous Materials Search Options

Select One or More Criteria:

Part/Subpart: Date:







Select Sections Issued: After

Search: ☒ Headers ☐ Text

Word Search Expression:

Word List: Link: or

OK Cancel

 Help  Navigator  Bookmark  Inquiry  Print  Reverse Course

Airworthiness Directives

Related Service Information

TYPE CERTIFICATES

Supplemental Type Certificates

ADVISORY CIRCULARS

Federal Aviation Regulations

Hazardous Materials

FAA HANDBOOKS

Figure 89




Figure 90






Figure 91

Gulfstream G-IV Library - 06/01/

 Browse  Search

IPC Search Options

Select One or More Criteria: ☒ Table of Contents ☐ Numerical Index

Manufacturer:

Model:

ATA Chapter:







Serial #:

Issued: Date:

Search: ☒ Headers ☐ Text

Word Search Expression:

Word List: Link:

 Help  Navigator  Bookmark  Inquiry  Print  Reverse Course

Maintenance Manual

Illustrated Parts Catalog

Service Information

Airworthiness Directives

Figure 92

Gulfstream G-IV Library - 06/01/

Service Information Search Options

Select One or More Criteria:

Manufacturer: **Gulfstream**

Model: **G-IV**

Issue Type: **↓**

Issue #: **↓**

ATA Applicability: **↓**

Compliance: **↓**

AD Cross Ref: **↓**

Select SI Issued: **After** **↓** Date: **↓**

Search: ☒ Headers ☐ Text

Word Search Expression: **↓**

Word List: **↓** Link: **↓** or **↓**

OK Cancel

Maintenance Manual

Illustrated Parts Catalog

Service Information

Airworthiness Directives

Help Navigator Bookmark Inquiry Print Reverse Course

Browse Search

Figure 93

ATP - US Federal Regulatory Library Alert Customer Bulletin Selection List					
Gulfstream					
Issue Number	Issue Date	Description	Status	ATA	AD (red on CD)
IV-107	06/13/90	Lighting. Thrust reverser lights capsules-Replacement	Recommend	33	
IV-108	Cancelled				
IV-109	Cancelled				
IV-110	01/24/89	Auto flight. Electronic display controllers	Mandatory	22	89-02-12
IV-111	04/27/89	Hydraulics. Ground spoiler hydraulic plumbing - Modification	Optional	24	
IV-112	06/09/89	Electrical Power. 300 Amp transformer-Rectifier with increase voltage capability	Optional	24	
IV-112 amend 1	12/21/90	Electrical Power. 300 Amp transformer-Rectifier with increase voltage capability	Optional	24	
113	03/22/91	Flight Controls. Aileron/Spoiler input hallcrank - Lubrication provisions	Optional	27	

Figure 94




Figure 95




Figure 96

ATP - US Federal Regulatory Library Revision Letter Selection List					
Document ID/ Revision Date	Publisher/ Pub Category	Description	Issue Date	Manufacturer/ Model	
US AU 43-13 03/25/92	DOT/FAA Alerts	February Alerts Issue 163	02/00/92	Various	
US AU 60-22 03/25/92	DOT/FAA Airmen ACs	Aeronautical Decision Making	12/31/91		
US AE 92-04-09E	DOT/FAA Small Engine ADs	To prevent engine failure caused by failure of the rocker shafthold down stud	02/27/92	Rolls Royce Limited RRTSIO-360 Series	

Figure 97








Figure 98

<div>  ATP - US Federal Regulatory Library ATP Publications Index and Fiche Finder </div>			
<div>  </div>			
Publisher	Category	Title	First Fiche
ATP		Gulfstream Master Index	
Gulfstream Aerospace	Airframe	Gulfstream G-I Maintenance Manual	AGC001


Help




Navigator




Bookmark




Inquiry




Print




Reverse Course




List




History



Zoom



Graphic








Figure 99






Figure 100

 ATP - US Federal Regulatory Library FAA Forms Selection List			
Number	Title	Last Revised Date	
337 -	Major Repair and Alteration	AGC001	
8010 -	Malfunction or Defect Report		
8110-14 -	Statement of Qualifications		
8130 -	Application for Export Certificate of Airworthiness		
8610-1 -	Mechanics Application for Inspection Authorization		
8610-2 -	Airman Certificate and/or Rating Application		

























Figure 101


[illegible]

Figure 102



ATP - US Federal Regulatory Library Forms BC-FORMS

FORM 98-3258 - PUBLICATION CHANGE REQUEST FORM



FOR: Publication
CIVIC (M244)

IN: Publication/Document
Pub L. 106-558
Statute, Title 5, USC 552

Document Change: Amend by deletion

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

FOR: Publication
CIVIC (M244)

IN: Publication/Document
Pub L. 106-558
Statute, Title 5, USC 552

Document Change: Amend by deletion

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion


Comments:

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552


Change: Amend by deletion

Comments:



ATP - US Federal Regulatory Library Forms BC-FORMS

FORM 98-3258 - PUBLICATION CHANGE REQUEST FORM



FOR: Publication
CIVIC (M244)

IN: Publication/Document
Pub L. 106-558
Statute, Title 5, USC 552

Document Change: Amend by deletion

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

FOR: Publication
CIVIC (M244)

IN: Publication/Document
Pub L. 106-558
Statute, Title 5, USC 552

Document Change: Amend by deletion

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

Publication To Be Changed

Pub L. 106-558
Statute, Title 5, USC 552

Change: Amend by deletion

Comments:

Figure 103




Figure 104




Figure 105




Figure 106




Figure 107

Gulfstream G-IV Library - 06/01/

System Setup Utilities

Current Configuration:

Password Security:	Enabled
System Hard Drive:	Drive C:
Path:	VATP
Space Allocation:	40 Mb
CD-ROM Drives:	2
CD-ROM Drive 1:	Drive E:
CD-ROM Drive 2:	Drive F:
Graphics Resolution:	1280 x 1024

Facility Information:

Name: _____
Address 1: _____
2: _____
3: _____
City: _____ St: _____ Zip: _____

Preferences:

Date Format: mm/dd/yy

OK Cancel

Help Navigator Bookmark Inquiry Print Reverse Course

User Setup System Setup Backup CD Update Tech Support




Figure 108

Gulfstream G-IV Library - 06/01/

System Setup Utilities

Current Configuration:

Password Security:	Enabled
System Hard Drive:	Drive C:
Path:	VATP
Space Allocation:	40 Mb
CD-ROM Drives:	2
CD-ROM Drive 1:	Drive E:
CD-ROM Drive 2:	Drive F:
Graphics Resolution:	1280 x 1024

Facility Information:

Name:
Address 1:
2:
3:
City: St: Zip:
Date Format: mm/dd/yy

Preferences:

OK Cancel

User Setup System Setup Backup CD Update Tech Support

Help Navigator Bookmark Inquiry Print Reverse Course




Figure 109



Gulfstream G-IV Library - 06/01/
▼ ▲

CD-ROM Update Utility

Product:

US Federal Regulatory Library

Expires:

93-15 July 15, 1993

Revision History:

Revision	Date First Used
92-13	///
92-14	///
92-15	///
92-16	///

Subscription Extension:

Product:

Subscription Code:

User Setup
 System Setup
 Backup
 CD Update
 Tech Support

Help
Navigator
Bookmark
Inquiry
Print
Reverse Course

Figure 112

113 / 113




Figure 113